

Attachment A: Digital Images

Page 1 of 5

November 10th, 2008

BOE Building 22nd Floor-Wide Post Mitigation Assessment
Sacramento, CA



- 1) Image of ambient air sampling location on West side of 3rd level garage building structure located at 450 N Street, Sacramento, California (Subject Building) at time of assessment.



- 2) Image of air sampling performed within northern side of the 22nd floor (construction office area) at time of clearance inspection and sampling assessment.



- 3) Image of air sampling equipment location operated within northeastern “punch out” window corner area of 22nd Floor at time of assessment.



- 4) Image of representative section where fire proofing material had been removed as part of the noted mitigative activity performed within the 22nd Floor.



- 5) Image of air sampling activity performed within room 2234 at eastern quadrant of the 22nd Floor mitigative area at time of assessment.



- 6) Image of floor structures and sampling equipment within southeast corner of the 22nd Floor mitigative area at time of assessment.



- 7) Image of sampling equipment location within southern perimeter quadrant of 22nd Floor mitigative area at time of assessment.



- 8) Image of air sampling performed within northwestern corner area of 22nd Floor mitigative area of subject building at time of assessment.



- 9) Additional image of air sampling performed within northwestern corner area of 22nd Floor mitigative area of subject building at time of assessment.



- 10) Image of ambient air sampling performed outside main entry at ground level at the conclusion of interior assessment.